



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
June 19, 2006

Supervisor 1027

Mine Name: Rhyolite #1
Operator Name: Color Country Rock
Preston Hafen
115 South Main
Veyo, Utah 84782

Permit number: S/021/032
Inspection Date: June 6, 2006
Time: 6:45 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Clear

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site while in the area.

Inspection Summary:

The site remains unchanged since my last inspection November 1, 2005. The site is stable with no environmental concerns.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

6/19/06

dj:pb

cc: Preston Hafen, Color Country Rock
Ed Ginouves, BLM, Cedar City FO, (UTU-79327)

O:\M021-Iron\S0210032-RhyoliteQuarry\inspections\06062006insp.doc